






DISPENSA junior slim




KESSEBÖHMER



<http://support.kesseboehmer.de/>






2 / 12



DISPENSA junior slim



1







2



FH	CH	CW	CD
551	640-728	≤ 160	≤ 490
606	695-783	≤ 160	≤ 490




3



DISPENSA junior slim



4




5





1x



PZ2



4x (6x)






DISPENSA junior slim



6



1x



7




1x





1x



PZ2






8x







DISPENSA junior slim





8






9



10




FH	X
551	532
606	586
















11



1x







12









13



14






15





1x






2x



PZ2




16






17



1x







18







PZ2



19



PZ2









20



PZ2



21



PZ2

